



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 042002744

Customer ID: ALIC62

Customer PO:

Project ID:

Attention: Christa Knorr
Alicon Environmental, Inc.
101 Stoney Creek Road
Clarks Summit, PA 18411

Phone: (570) 563-2719

Fax: (570) 563-1505

Received Date: 02/01/2020 08:20 AM

Analysis Date: 02/01/2020

Collected Date: 01/31/2020

Project: SSD - South Scranton Intermediate

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures ≥0.5μ < 5μ	≥5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	(S/cc)
SSIS-01 042002744-0001	Wood Shop	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-02 042002744-0002	Ground Floor Hallway No. 2	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-03 042002744-0003	Cafeteria A	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-04 042002744-0004	Auditorium	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-05 042002744-0005	1st Floor Main Corridor	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-06 042002744-0006	Girls Locker Room 110	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-07 042002744-0007	Gymnasium	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-08 042002744-0008	Room 206	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-09 042002744-0009	2nd Floor Left Corridor	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-10 042002744-0010	Room 317	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-11 042002744-0011	3rd Floor Left Corridor	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049
SSIS-12 042002744-0012	Room 312	1200.00	0.0660	0	None Detected	0	0	0.0049	<15.00	<0.0049

Analyst(s)

Ted Young (12)

Samantha Rundstrom, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. EMSL is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. Samples received in good condition unless otherwise noted. The test results meet the requirements of NELAC unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367, LA #04127

Initial report from: 02/01/2020 14:17 PM